

[Quick Links: Skip to main page content](#) [Skip to Search](#) [Skip to Topics Menu](#) [Skip to Common Links](#)

## Medical & Radiation Emitting Device Recalls

### Class 2 Recall Zimmer NexGen LPS



<b>Date Posted</b>	December 02, 2010
<b>Recall Number</b>	Z-0532-2011
<b>Product</b>	Zimmer, NexGen Complete Knee Solution LPS Femoral Component, Size E Right, sterile, REF 00-5996-015-02.
<b>Code Information</b>	61494589
<b>Recalling Firm/ Manufacturer</b>	Zimmer Inc. 1800 W Center St Warsaw, Indiana 46580-2304
<b>For Additional Information Contact</b>	Cheryl Trease 574-267-6131
<b>Reason for Recall</b>	These lots of Zimmer NexGen Complete Knee Solution LPS Femoral Component and Zimmer NexGen Complete Knee Solution LPS Flex Gender Femoral Component exhibit a nonconforming internal CAM radius. The condition is intermittent and not all devices have nonconforming geometry.
<b>Action</b>	The firm sent URGENT DEVICE CORRECTION AND REMOVAL notices to distributors and sales staff, Risk Managers, and implanting surgeons dated 9/15/2010. Sales staff and risk managers were

instructed to return any product on hand.  
Surgeons were informed of the issue but there was no action to be taken by surgeons.

**Quantity in Commerce** 192 all sizes of 5996.

**Distribution** US, Germany, Spain, France, UK, Italy, Sweden, South Africa, Czech Republic, Bulgaria, Poland, Romania, and Austria.